


IF IN DOUBT-ASK



(1) 3 WIRE RTD: R = RED & W = WHITE
NB: MONITORING SYSTEM IS EARTHED

(2) K1 & K2 ENABLE FUNCTION TO BE ENABLED BY CONTACT.
FOR USE AS DISABLE FUNCTION UNDER NORMAL OR FAULT
OPERATION, REFER TO FACTORY FOR CONTACT RATING.

CERTIFIED PRINT (ONLY IF SIGNED) BY	MACHINE HV	OTHER FEATURES
DATE	CONTROL MA330	PH SYSTEM
DRAWN AGS	POLES 4	
CHK'D JMS	No. OF ENDS 4	
APP'D ADV	SENSING 3	
	PHASE C	
	DRG. SIZE A8-1729	ISSUE A
	SHEET 1 OF 1	SHEETS

4-0851-01	A	AGS	19/03/08	ORIGINAL ISSUE.
MOD.	ISSUE	DRAWN	DATE	ALTERATION

WIRING DIAGRAM